

Oil Field Environmental Incident Summary

Incident: 20150324154051 **Date/Time of Notice:** 03/24/2015 15:40

Responsible Party: CONDOR PETROLEUM, INC.

Well Operator: CONDOR PETROLEUM, INC.

Well Name: FEDERAL 2-1

Field Name: STONEVIEW

Well File #: 13348

Date Incident: 3/24/2015 **Time Incident:** 00:15

Facility ID Number:

County: DIVIDE

Twp: 160

Rng: 95

Sec: 2

Qtr: SE SW

Location Description:

Submitted By: JoAnn Klevenberg

Received By:

Contact Person: Steve Tracy
216 16TH STREET SUITE 1750
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other - List Under Desc of Cause below

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	50	Barrels	50	Barrels		

Description of Other Released Contaminant:

plug blew out on sw pump, was contained with in the dike, Cororan is vac up the dike (appx. 50 bbls)

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

contained with in the dike

Potential Environmental Impacts:

none

Action Taken or Planned:

vac up sw with in the dike, hauled to disposal

Wastes Disposal Location: haul to disposal

Agencies Involved:

Updates

Date: 3/24/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the company contact, this spill occurred on location along a line for the produced water pump. The spill remained within the dikes. NDIC retains oversight.